### DECATUR URBANIZED AREA TRANSPORTATION STUDY

## PUBLIC NOTICE TRANSPORTATION IMPROVEMENT PLAN

Notice is given by the Decatur Urbanized Area Transportation Study (DUATS) that they have an amendment on file for the Fiscal Year 2023-2026 Transportation Improvement Program (TIP) for the public's review and comments. The fiscal year covers the period of July 1 through June 30. The TIP describes the major transportation improvements planned to be undertaken during the next four (4) years within the Decatur Metropolitan Planning Area (MPA). The TIP was jointly developed by the member agencies of DUATS.

Hard copies of these documents are available at the following locations:

- ◆ Decatur Public Library, Reference Desk, 130 North Franklin Street
- ◆ Economic & Community Development Department, 3<sup>rd</sup> Floor, Decatur Civic Center
- ◆ Planning & Zoning Office, Room 501, Macon County Office Building, 141 S. Main Street
- ◆ Forsyth Village Hall, 301 South Route 51
- ◆ Forsyth Public Library, 268 South Elwood
- ◆ Mt. Zion Village Hall, 1400 Mt. Zion Parkway
- ◆ Mt. Zion Public Library, 115 West Main Street
- ◆ Decatur Public Transit System Administration Building, 555 East Wood
- ◆ Decatur Park District, District Office, 620 East Riverside Avenue
- ◆ Senator Severns Transit Center, 353 East William Street
- ◆ Oreana Public Library, 211 S. Route 48, Oreana
- ◆ Barclay Public Library, 220 S. Main Street, Warrensburg
- ◆ Online at: http://www.decaturil.gov/citygovernment/duats/documents.html

Your comments are important, and you are encouraged to express them. Written comments or questions should be directed to DUATS, #1 Gary K. Anderson Plaza, Decatur, IL 62523. Comments may also be sent by E-mail to DUATS@decaturil.gov. All comments received prior to May 15, 2023, will be considered before the TIP is amended.

Cordaryl Patrick
DUATS Study Director

**TIP AMENDMENT #7** 

## Existing Projects in the Annual Element of the FY 2023 – 2026 TIP

# TIP Amendment # 7 State of Illinois Highway Improvement Program Annual Element FY 2023

State ID No.	Project Location	Length in Miles	Project Description	Cost Estimates (in 1,000's)					Funding Sources (in 1,000's)			Type of	Source
				Total Cost	Const.	R.O.W.	Eng/ Design	Utility	Federal	State	Local	Funds	of State Match
7-50927-0000	US 51 from Dewitt Co Line to 0.1 Mi N of Forsyth Rd	8.14	Resurfacing	\$29,340.00	\$29,340.00				\$23,472.00	\$5,868.00		NHPP State- Federal	NHPP - State Match
7-51015-0000 7-76910-8711	US 51 from 0.1 Mi N of Forsyth Rd to I 72 in Decatur	1.94	Resurfacing and ADA improvements	\$9,300.00	\$9,300.00				\$7,505.00	\$1,795.00		NHPP State- Federal; PROTEC T-State- Federal; HSIP Safety- State- Federal	NHPP - State Match; Restricted State Match
7-51350-0000 7-51350-0500 7-76910-8714	US 36 from ILL 48 to Church St in Decatur & W Eldorado St from ILL 48 to US 36	1.22	Resurfacing And ADA improvements structure repair and traffic signal modernization and replacement	\$5,050.00	\$5,050.00				\$4,240.00	\$810.00		NHPP State- Federal; STP - URB 5- 200K-S-F HSIP Safety- State- Federal	NHPP- State Match; Restricted State Match; State Match
7-93940-0600	I-72 Over ILL 121 & IC RR NW of Decatur	0	RR Flagger Agreement	\$300.00				\$300.00	\$0.00	\$300.00			State Only
7-50912-0000 7-50912-0500	ILL 48 from Bowman Rd to Christian Co Line	9.86	Resurfacing, ADA Improvements and Culvert Replacement	\$8,360.00	\$8,360.00				\$6,688.00	\$1,672.00		STP-Rural State- Federal; Hwy-Inf- BFP-S- Federal	State Match
7-50942-0000	ILL 105 from 0.3 Mi E of Bender Dr to Piatt Co Line	6.06	Resurfacing	\$4,040.00	\$4,040.00				\$3,232.00	\$808.00		STP-Rural State- Federal; STBG PGM-50K to 200K- S(IIJA)- Federal	State Match
7-50369-0000	ILL 121 from 0.6 Mi NW of I- 72 to University Ave in Decatur	2.72	Resurfacing and ADA improvements	\$6,550.00	\$6,550.00				\$5,240.00	\$1,310.00		NHPP State- Federal	NHPP - State Match
7-50871-0000 7-76910-8724	ILL 121 from US 36 to SCL of Mt Zion	4.15	Resurfacing, ADA improvements and traffic signal modernization and replacement	\$10,940.00	\$10,940.00				\$8,906.00	\$2,034.00		NHPP State- Federal HSIP Safety- State- Federal	NHPP - State Match; Restricted State Match
0-01494-7001	ILL 105 at Int of ILL 105 & Country Club Rd in Decatur	0	Traffic Signal Modernization	\$325.00	\$325.00				\$260.00	\$65.00		STBG- PGM 50K to 200K-S (IIJA)- Federal	State Match
7-52871-0000	I-72 Over ILL 48 2.5 Mi E of Forsyth	0	Bridge Repair	\$520.00	\$520.00				\$468.00	\$52.00		NHPP State- Federal	NHPP - State Match
0-01376-7002	I-72 / US 51 - Various Locations in Macon County	0	Bridge Painting	\$1,240.00	\$1,240.00				\$992.00	\$248.00		STP-Stwd Flex State- Federal	State Match

# Proposed Projects in the Annual Element of the FY 2023 – 2026 TIP TIP Amendment # 7 State of Illinois Highway Improvement Program Annual Element FY 2023

Project Location US 51 from	in Miles											Source of State Match
US 51 from	Length in Miles	Project Description	Total Cost	Const.	R.O.W.	Eng/ Design	Utility	Federal	State	Local	Type of Funds	
Dewitt Co Line to 0.1 Mi N of Forsyth Rd	8.14	Resurfacing	\$26,540.00	\$26,540.00				\$21,232.00	\$5,308.00		NHPP State- Federal	NHPP - State Match
JS 51 from 0.1 Mi N of Forsyth Rd to I- 72 in Decatur	1.94	Resurfacing and ADA improvements	\$9,300.00	\$9,300.00				\$7,505.00	\$1,795.00		NHPP State- Federal; HSIP Safety- State- Federal	NHPP - State Match; Restricted State Match
IS 36 from ILL 48 to Church St in Decatur & W Eldorado St from ILL 48 to US 36	1.22	Resurfacing and ADA improvements structure repair and traffic signal modernization and replacement	\$5,050.00	\$5,050.00				\$4,240.00	\$810.00		NHPP State- Federal; STBG 50- 200K-S- Urban (IIJA)- Federal HSIP Safety- State- Federal	NHPP- State Match; Restricted State Match; State Match
I-72 Over ILL 121 & IC RR IW of Decatur	0	RR Flagger Agreement	\$300.00				\$300.00	\$0.00	\$300.00			State Only
ILL 48 from Bowman Rd to Christian Co Line	9.86	Resurfacing, ADA Improvements and Culvert Replacement	\$8,360.00	\$8,360.00				\$6,688.00	\$1,672.00		STP-Rural- State- Federal; Hwy-Inf- BFP-S- Federal	State Match
ILL 105 from 0.3 Mi E of Bender Dr to Piatt Co Line	6.06	Resurfacing	\$4,040.00	\$4,040.00				\$3,232.00	\$808.00		STP-Rural- State- Federal; STBG PGM-50K to 200K- S(IIJA)- Federal	State Match
ILL 121 from .6 Mi NW of I- 72 to Jniversity Ave in Decatur	2.72	Resurfacing and ADA improvements	\$13,080.00	\$13,080.00				\$10,464.00	\$2,616.00		NHPP State- Federal	NHPP - State Match
ILL 121 from JS 36 to SCL of Mt Zion	4.15	Resurfacing, ADA improvements and traffic signal modernization and replacement	\$10,940.00	\$10,940.00				\$8,906.00	\$2,034.00		NHPP State- Federal HSIP Safety- State- Federal	NHPP - State Match; Restricted State Match
LL 105 at Int f ILL 105 & Country Club d in Decatur	0	Traffic Signal Modernization	\$325.00	\$325.00				\$260.00	\$65.00		STBG- PGM 50K to 200K-S (IIJA)- Federal	State Match
I-72 Over ILL 18 2.5 Mi E of Forsyth	0	Bridge Repair	\$520.00	\$520.00				\$468.00	\$52.00		NHPP State- Federal	NHPP - State Match
I-72 / US 51 - Various Locations in Macon County	0	Bridge Painting	\$1,240.00	\$1,240.00				\$992.00	\$248.00		STP-Stwd Flex State- Federal	State Match
13   5072	S 51 from 0.1 Mi N of Drsyth Rd to I 2 in Decatur  S 36 from ILL 8 to Church it in Decatur W Eldorado t from ILL 48 to US 36  -72 Over ILL 121 & IC RR W of Decatur  ILL 48 from Downan Rd to Christian Co Line  LL 105 from 0.3 Mi E of Bender Dr to Piatt Co Line  LL 121 from 6 Mi NW of I- 72 to niversity Ave in Decatur  LL 121 from S 36 to SCL of Mt Zion  L 105 at Int ILL 105 & Downan Rd to Downan Rd to Christian Co Line  LL 121 from S 36 to SCL of Mi NW of I- 72 to Diversity Ave in Decatur  LL 121 from S 36 to SCL of Mt Zion  L 105 at Int ILL 105 & Downan Rd to Christian Co Line  LL 121 from S 36 to SCL of Mt Zion  L 105 at Int ILL 105 & Downan Rd ILL 105 & Do	S 51 from 0.1 Mi N of orsyth Rd to 1 2 in Decatur  S 36 from ILL 8 to Church it in Decatur W Eldorado t from ILL 48 to US 36  1.22 W Eldorado t from ILL 48 to US 36  LLL 121 & IC RR W of Decatur  LLL 121 & IC RR W of Decatur  LLL 121 from 6 Mi NW of 1- 72 to niversity Ave in Decatur  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 6 Mi NW of 1- 72 to niversity Ave in Decatur  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 5 dender Dr to briatt Co Line  LLL 121 from 5 dender Dr to briatt Co Line  LLL 122 from 5 dender Dr to briatt Co Line  LLL 123 from 5 dender Dr to briatt Co Line  LLL 125 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  LL 122 from 5 dender Dr to briatt Co Line  LLL 123 from 6 dender Dr to briatt Co Line  LLL 124 from 6 dender Dr to briatt Co Line  LLL 125 from 6 dender Dr to briatt Co Line  LLL 125 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  LLL 122 from 6 dender Dr to briatt Co Line  LLL 123 from 6 dender Dr to briatt Co Line  LLL 124 from 6 dender Dr to briatt Co Line  LLL 125 from 6 dender Dr to briatt Co Line  LLL 126 from 6 dender Dr to briatt Co Line  LLL 127 from 6 dender Dr to briatt Co Line  LLL 128 from 9 dender Dr to briatt Co Line  LLL 129 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line  B dender Dr to briatt Co Line  LLL 122 from 6 dender Dr to briatt Co Line  LLL 123 from 6 dender Dr to briatt Co Line  LLL 124 from 6 dender Dr to briatt Co Line  LLL 125 from 6 dender Dr to briatt Co Line  LLL 126 from 6 dender Dr to briatt Co Line  LLL 127 from 6 dender Dr to briatt Co Line  LLL 128 from 6 dender Dr to briatt Co Line  LLL 129 from 6 dender Dr to briatt Co Line  LLL 121 from 6 dender Dr to briatt Co Line	Resurfacing and ADA improvements  3 36 from ILL 8 to Church tin Decatur W Eldorado t from ILL 48 to US 36  1.22  1.22  Resurfacing and ADA improvements structure repair and traffic signal modernization and replacement  72 Over ILL 121 & IC RR W of Decatur  ILL 48 from Downan Rd to Christian Co Line  1.23  Resurfacing and ADA improvements structure repair and traffic signal modernization and replacement  Resurfacing, ADA Improvements and Culvert Replacement  1.24  Resurfacing, ADA Improvements and Culvert Replacement  1.25  Resurfacing and ADA improvements and Culvert Replacement  1.26  Resurfacing and ADA improvements and Culvert Replacement  1.27  Resurfacing and ADA improvements and Culvert Replacement  1.28  Resurfacing and ADA improvements and Culvert Replacement  1.29  Resurfacing and ADA improvements and Culvert Replacement  1.20  Resurfacing and ADA improvements and Culvert Replacement  1.21  Resurfacing and ADA improvements and Culvert Replacement  1.27  Resurfacing and ADA improvements and Culvert Replacement  1.29  Resurfacing and ADA improvements and Culvert Replacement  1.20  Resurfacing and ADA improvements and Culvert Replacement  1.21  Resurfacing and ADA improvements and Culvert Replacement  1.27  Resurfacing and ADA improvements and Culvert Replacement  1.29  Resurfacing and ADA improvements and Culvert Replacement  1.20  Resurfacing and ADA improvements and Culvert Replacement  1.21  Resurfacing and ADA improvements and Culvert Replacement  1.22  Resurfacing and ADA improvements and Culvert Replacement  1.22  Resurfacing and ADA improvements and Culvert Replacement  1.22  Resurfacing and ADA improvements and Culvert Replacement  1.23  Resurfacing and ADA improvements and Culvert Replacement  1.24  Resurfacing and ADA improvements and Culvert Replacement  1.25  Resurfacing and ADA improvements and Culvert Replacement  1.27  Resurfacing and ADA improvements and Culvert Replacement  1.29  Resurfacing and ADA improvements and Culvert Replacement	Resurfacing and ADA improvements  3 36 from ILL 8 to Church to I 2 in Decatur  W Eldorado to Improvements  To US 36  Resurfacing and ADA improvements  To US 36  Resurfacing and ADA improvements structure repair and traffic signal modernization and replacement  Resurfacing and ADA improvements structure repair and traffic signal modernization and replacement  Resurfacing, ADA Improvements and Culvert Replacement  Resurfacing \$8,360.00  Resurfacing \$4,040.00  Resurfacing \$4,040.00  Resurfacing \$13,080.00  Resurfacing \$13,080.00  Resurfacing \$13,080.00  Resurfacing \$13,080.00  Resurfacing \$13,080.00  Resurfacing \$13,080.00  Resurfacing \$1,040.00  Resurfacing \$1	1.94   Resurfacing and ADA improvements   1.94   Resurfacing and ADA improvements   1.94   Resurfacing and ADA improvements   1.95   Resurfacing and ADA improvements   1.95   Resurfacing and ADA improvements   1.22   Resurfacing and replacement   1.22   1.22   Resurfacing and replacement   1.22   1.22   Resurfacing and Resurfacing and replacement   1.23   1.24   1.25	S. 51 from 0.1   Mi N of 1   Styte Result   Styte	1.94   Resurfacing and ADA   Sp.300.00   Sp.300.00	1.94   Resurfacing and ADA improvements   Sp.300.00   Sp.300.00	S   51 from 0.1   Mil N of Display Ref to 1   1.94   Resurfacing and ADA Improvements   53,000.00   59,300.00   57,505.00	Resurfacing and ADA improvements   Sp. 200.00   Sp. 300.00   Sp. 300	1.94   Resultating and ADA improvements   1.94   Resultating and ADA improvements   1.05 at Int   1.05 at Int	Section   1.94   Sect